

Districtwide Emergency Building Repair Workbook (MEASURE H)
July 1, 2018 - June 30, 2019

College Projects			\$ 737,421
Proj #	Description	Project List Reference	Measure H
177	B3 - remove tile floors and replace w/ carpet	I.N	\$ 4,451
183	CAN B21 - sump pump	I.D	\$ 22,045
184	Removal of fire hazard and poison oak on Canada Road	I.O	\$ 37,822
193	Install Solar Crossing by Lot 11 for student safety	I.R	\$ 13,030
199	Repair light poles due to unsafe conditions	I.D	\$ 16,350
210	Replace two malfunctioned split systems on campus to prevent leaks	I.D	\$ 7,040
219	Replace damage smoke curtain	I.D	\$ 2,155
237	Repair classroom door entry that's not closing properly	I.D	\$ 1,917
249	Update Time Clocks per Design Standards	G	\$ 10,588
256	Remove hazardous material from CAN B13 elevator per state requirement	I.F	\$ 3,012
280	Replaced two defective tower motors to keep system operating efficiently and effectively	I.D	\$ 14,564
	Total Encumbered		\$ 132,974
	Available Balance		\$ 604,448
College of San Mateo Projects			\$ 718,833
Proj #	Description	Project List Reference	Measure H
178	CSM B36 - repair Planetarium insulation	I.D	\$ 5,000
179	CSM B12 - replace and purchase additional five MNL5RR3 VAV controllers	I.D	\$ 1,600
180	CSM B1 - air conditioning unit repair	I.D	\$ 4,000
181	Repair plaster in instructional pool	I.D	\$ 2,000
182	CSM B10 Bookstore - install energy efficient film on windows	I.L	\$ 2,150
187	Replace DO Chiller/DX unit Eaton soft starter controller	I.D	\$ 6,500
188	Improve pathway to B5 entrance for persons with disabilities	I.C	\$ 45,000
189	B6 Observatory - reroute and augment electrical power outlets for electrical safety	I.D/I.H	\$ 1,600
190	Replaced failing central chiller plant #2 thermal expansion valve	I.D	\$ 2,200
194	Replace failed DO server room conditioning unit condenser to ensure longevity of ITS equipment	I.D	\$ 24,000
195	Replaced failed door closers in B18 and new locksets in B1 and B9	I.H	\$ 5,000
196	Repair failed main air handler monitor in B9	I.D	\$ 2,200
197	De-compact Football field as it is out of compliance	I.L	\$ 3,500
198	Repair circulation/display pumps/filter fountain in B1, B9, B10	I.D	\$ 25,000
201	Replace failed domestic hot water pump in B1	I.D	\$ 1,000
202	Install energy efficient film on windows at District Office	I.D/I.L	\$ 5,707
203	Replaced failed AC compressor unit at District Office	I.D	\$ 40,000
204	Repair clogged sewer causing back up of raw sewage	I.D	\$ 1,200
205	Replace and additional camera in SMAC for safety and prevent burglary	M	\$ 6,500
207	Replace failed pool controller modems	I.D	\$ 2,800
208	Replaced fail instructional pool lights for safety and required by SM County Health Dept	I.D.H	\$ 22,000
209	Remove dead trees, clear out brushes around B7 and parking for fire safety	I.O	\$ 30,000
212	Replace spill kits and chemical injection pumps to prevent chemical release	I.D.L	\$ 10,000
213	Replaced failed filters to prevent hazards to swimmers in the Olympic Pools	I.D.I	\$ 2,000

